REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/20/2023	**Time:**	10:50 AM
Name of School Corporation:	PRIMROSE WEST CARMEL			**Corp ID:**	1100382
Address of School Corporation:	3746 W. 96th st				
City:	Carmel **Zip:**	46032		**County Number:**	29
VIN:	1GBHG31C181231394	**License Number:**	B115K	**Bus Number:**	A1
Make of Body:	Chevrolet **Year:** 2008	**Make of Chassis:**	Collins Bus Corporation	**Year:**	2008
Bus Type:	A1	**Mileage:**	67860		
Inspection Status:	O **Inspected By:**	Joel Flores		**PE:**	7415

Violations - Rejected

Inspection Code	Description
68-1-4	See Notes: Any defect inspector deems a violation not listed
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

Inspection Code	Description
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
50-2-2	The seat belt cutter does not have a full width handgrip, with a protective blade to minimize risk

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**