# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 4/20/2023 | **Time:** | 12:22 PM |
| **Name of School Corporation:** | TWIN LAKES SCHOOL CORPORATION | | | **Corp ID:** | 918565 |
| **Address of School Corporation:** | | | | | |
| **City:** | | **Zip:** | | **County Number:** | 91 |
| **VIN:** | 1FDFE4FP0ADA40222 | **License Number:** | 84335 | **Bus Number:** | 38 |
| **Make of Body:** | Ford **Year:** 2010 | **Make of Chassis:** | Collins Bus Corporation | **Year:** | 2010 |
| **Bus Type:** | A2 | **Mileage:** | 95641 | | |
| **Inspection Status:** | O | **Inspected By:** | Nate King | **PE:** | 7421 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 22-1-1 | A dripping oil or fluid leak |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**