REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/1/2023	**Time:**	9:21 AM
Name of School Corporation:	EDINBURGH COMM. SCHOOL CORP.			**Corp ID:**	414215
Address of School Corporation:	202 S Keeley St				
City:	Edinburg	**Zip:**	46124	**County Number:**	41
VIN:	1GB3G2BG4B1160642	**License Number:**	9225	**Bus Number:**	21
Make of Body:	Chevrolet **Year:** 2011	**Make of Chassis:**	Chevrolet	**Year:**	2011
Bus Type:		**Mileage:**	46612		
Inspection Status:	O	**Inspected By:**	Brandon Steffee	**PE:**	8247

Violations - Rejected

Inspection Code	Description
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description