REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual 5/1/2023 **Time**: Date: 9:21 AM

Name of School Corporation: EDINBURGH COMM. SCHOOL CORP. Corp ID: 414215

Address of School Corporation: 202 S Keeley St

City: Edinburg Zip: 46124 **County Number: 41** VIN: 1GB3G2BG4B1160642 License Number: 9225 **Bus Number:** 21 Make of Body: Chevrolet Year: 2011 Make of Chassis: Chevrolet Year: 2011

46612 Bus Type: Mileage:

Inspection Status: O Inspected By: Brandon Steffee PE: 8247

Violations - Rejected

Inspection Description <u>Code</u>

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any 23-1-3 direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description