

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/2/2023	Time:	10:05 AM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625
Address of School Corporation:	PO Box 550				
City:	Converse	Zip:	46919	County Number:	52
VIN:	4UZABRDT2FCFW5637	License Number:	1115	Bus Number:	3
Make of Body:	Thomas Built Buses, Inc.	Year:	2013	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	100335	Year:	2015
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.