

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 5/3/2023 **Time:** 10:31 AM
Name of School Corporation: LOGANSPORT COMM. SCHOOL CORP. **Corp ID:** 90875
Address of School Corporation: 2829 George St
City: Logansport **Zip:** 46947 **County Number:** 9
VIN: 1HA6GUBG8KN007349 **License Number:** 22917 **Bus Number:** 191
Make of Body: Starcraft **Year:** 2019 **Make of Chassis:** Chevrolet **Year:** 2019
Bus Type: A2 **Mileage:** 78523
Inspection Status: O **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 82-1-2 | The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49 |
| 41-1-5 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) |
| 41-1-7 | Non safety related signs/decorations posted. |
| 11-1-2 | The front or rear bumper is not properly attached, missing, torn, loose, or altered. |
| 70-1-4 | There is any cracked glass to the immediate right or left of the driver |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|-------------------------------------|
| 59-2-4 | Stop arm does not function properly |

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.