

# REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Semi-Annual      **Date:** 4/26/2023      **Time:** 10:47 AM  
**Name of School Corporation:** NORTHEAST SCHOOL CORPORATION      **Corp ID:** 777645  
**Address of School Corporation:** PO Box 493  
**City:** Hymera      **Zip:** 47855      **County Number:** 77  
**VIN:** 1GBJG31F021235987      **License Number:** 44502      **Bus Number:** 35  
**Make of Body:** Mid Bus, Inc. **Year:** 2003      **Make of Chassis:** IC Corporation **Year:** 2003  
**Bus Type:**      **Mileage:** 76256  
**Inspection Status:** O      **Inspected By:** Byron Goodman      **PE:** 7008

## Violations - Rejected

### Inspection Code Description

## Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 10-2-2                 | The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design) |

### Bus Type Description