

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	5/9/2023	<b>Time:</b>	1:41 PM
<b>Name of School Corporation:</b>	FIRST STUDENT - INDPLS	<b>Corp ID:</b>	4981		
<b>Address of School Corporation:</b>	xxx	<b>City:</b>	Indianapolis	<b>Zip:</b>	46202
<b>VIN:</b>	1T88Y9D23M1175465	<b>License Number:</b>		<b>County Number:</b>	49
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2020	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	41476	<b>Year:</b>	2020
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Joel Flores	<b>PE:</b>	7415

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative
3-1-7	Battery compartment door is not securely fastened.
3-1-3	Any battery is loose in its mounting.
64-1-4	Any front turn signal does not function properly
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
70-1-2	There are intersecting cracks in the windshield area covered by the wipers
70-1-3	There are any breaks, nicks or chips larger than 3/4 inch in diameter in the area covered by the wipers on the drivers' side
7-1-5	See Notes: Any defect inspector deems a violation not listed
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
18-2-3	Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber)
59-2-1	Any stop arm light is inoperative
3-2-2	Wiring is exposed.
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged

metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

- 63-2-1 Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord
- 53-2-5 "U" bolts are loose, broken, or missing
- 25-2-1 Mountings are broken or bent badly enough to inhibit proper adjustment
- 51-2-1 The service door does not open or close properly
- 69-2-1 Wipers fail to function

### **Bus Type Description**

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**