## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:5/10/2023 Time:9:10 AM

Name of School Corporation: EAST GIBSON SCHOOL CORPORATION Corp ID: 262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number:26VIN:1GB6G3AG8A1145550License Number:2370Bus Number:21Make of Body:Star Trans Year:2010Make of Chassis:ChevroletYear:2010

Bus Type: Mileage: 140511

Inspection Status: A Inspected By: Bradley Miller PE: 7809

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

**Bus Type Description**