

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 5/11/2023 **Time:** 10:31 AM
Name of School Corporation: BENTON COMMUNITY SCHOOL CORP. **Corp ID:** 40395
Address of School Corporation: PO Box 512
City: Fowler **Zip:** 47944 **County Number:** 4
VIN: 4DRBUAAN9DB329248 **License Number:** 4882 **Bus Number:** 1239
Make of Body: IC Corporation **Year:** 2012 **Make of Chassis:** IC Corporation **Year:** 2012
Bus Type: C **Mileage:** 82220
Inspection Status: O **Inspected By:** Nate King **PE:** 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.