## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	5/17/2023	Time:	11:04 AM
Name of School Co	orporation: TRI-C	COUNTY SCHO	OL CORPORATION	N	Corp ID:	918535
Address of School Corporation:						
City:		Zip:			<b>County Number:</b>	91
VIN:	4DRBUC8N3LB5664	94	License Number:	B451N	Bus Number:	1
Make of Body:	IC Corporation Year:	2018	Make of Chassis:	IC Corporation	Year:	2020
Bus Type:			Mileage:	45392		
Inspection Status:	R	Inspected By:	Nate King		PE:	7421

## Violations - Rejected

Inspection CodeDescription52-1-2Any shock absorber is leaking fluid

## Violations - Out of Service

Inspection Code Description

**Bus Type Description**