

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/18/2023	Time:	9:55 AM		
Name of School Corporation:	MONROE-GREGG SCHOOL DISTRICT			Corp ID:	555900		
Address of School Corporation:	205 S Chestnut St						
City:	Monrovia	Zip:	46157	County Number:	55		
VIN:	4DRBUC8P8MB492220		License Number:	23960	Bus Number:	33	
Make of Body:	IC Corporation	Year:	2020	Make of Chassis:	IC Corporation	Year:	2021
Bus Type:	C			Mileage:	29356		
Inspection Status:	O	Inspected By:	Mike Adams	PE:	7407		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-2	The headlight dimmer switch fails to operate properly
34-1-3	The optional flashing headlights do not flash in an alternating manner
52-1-4	Any shock absorber is broken or missing
18-1-2	See Notes: Any defect inspector deems a violation not listed
67-1-2	Rims are bent or loose
27-1-1	Any openings are not sealed or plugged
48-1-2	There are loose lines, fittings, or hoses
48-1-1	Power steering unit leaks at any point
82-1-2	See Notes: Any defect inspector deems a violation not listed
33-1-2	The grill is missing
33-1-1	The grill has any exposed edges that may cause injury
64-1-4	Any front turn signal does not function properly
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
29-1-3	There are holes in the floor
53-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
53-1-1	One (1) leaf spring is broken under the first two (2) leaves

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
67-2-1	Rim or wheel discs have visible cracks, elongated bolt holes or any indication of repair by welding

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.