REPORT OF SCHOOL BUS INSPECTION

Type of 10:58 Time: Annual Date: 5/30/2023 Inspection: AM **AUXILIO SERVICES (MUNCIE)** 251807 Name of School Corporation: Corp ID: **Address of School Corporation:** 11260 Cornell Park Dr Suite 700 County City: Cincinnati Zip: 45242 18 Number: License VIN: 4UZABRDT9JCJF1837 B759N Bus Number: M21 Number: Thomas Built Buses, Year: 2016 Thomas Built Buses, Year: Make of Make of Body: 2018 Chassis: Inc. Bus Type: С Mileage: 67841 Inspection Inspected R PE: Steve Spallinger 6921 Status: By:

Violations - Rejected

Inspection

<u>Inspection</u> <u>Code</u>	<u>Description</u>
52-1-1	There are any loose, broken, or missing mountings
	The first aid kit is not complete: One (1) package adhesive bandages; containing a total
	of sixteen (16) 1" x 3" handages 1 roll 1"x5vd 1 blunt scissor 6 3x3" gauze pads

of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads 28-1-4 (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2

triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.