

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 5/25/2023 **Time:** 12:44 PM
Name of School Corporation: ELWOOD COMMUNITY SCHOOL CORP. **Corp ID:** 485280
Address of School Corporation: 1306 N Anderson St
City: Elwood **Zip:** 46036 **County Number:** 48
VIN: 4DRBUSKP79B673965 **License Number:** 32009 **Bus Number:** 3
Make of Body: IC Corporation **Year:** 2007 **Make of Chassis:** IC Corporation **Year:** 2007
Bus Type: C **Mileage:** 96500
Inspection Status: R **Inspected By:** Jeremy Mason **PE:** 8139

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.