

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/31/2023	Time:	9:48 AM		
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			Corp ID:	251807		
Address of School Corporation:	11260 Cornell Park Dr Suite 700						
City:	Cincinnati	Zip:	45242	County Number:	18		
VIN:	4DRBUC8P6JB593445		License Number:	B613T	Bus Number:	M38	
Make of Body:	IC Corporation	Year:	2016	Make of Chassis:	IC Corporation	Year:	2018
Bus Type:	C			Mileage:	39720		
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
60-1-1	Sun visor is missing, cracked or broken
29-1-5	Prohibited area sign is missing or obscured
29-1-4	Prohibited area line is missing or improper

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.