## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:5/31/2023Time:9:48 AMName of School Corporation:AUXILIO SERVICES (MUNCIE)Corp ID:251807

Address of School Corporation: 11260 Cornell Park Dr Suite 700

City:CincinnatiZip:45242County Number:18VIN:4DRBUC8P6JB593445License Number:Bus Number:M38Make of Body:IC Corporation Year:2016Make of Chassis:IC Corporation Year:2018

Bus Type: C Mileage: 39720

Inspection Status: O Inspected By: Steve Spallinger PE: 6921

## Violations - Rejected

## Inspection CodeDescription60-1-1Sun visor is missing, cracked or broken29-1-5Prohibited area sign is missing or obscured29-1-4Prohibited area line is missing or improper

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.