REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	5/31/2023	Time:	10:35 AM
Name of School Address of School	Corporation: Al	UXILIO SERVICI 11260 Corne	ES (MUNCIE) ell Park Dr Suite	700	Corp ID:	251807
City:	Cincinnati	Zip:	45242		County Number:	18
VIN:	1T7Y74D25J1123017		License Number:	B546N	Bus Number:	M24
Make of Body:	Thomas Built Buses, Year	ear: 2016	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2018
Bus Type:	D		Mileage:	45264		
Inspection Status:	0	Inspected By:	Steve Spallinge	er	PE:	6921

Violations - Rejected

Inspection Code	<u>Description</u>		
63-1-3	Any front tire has less than 4/32 inch tread depth when measured in any two adjacent major grooves		
23-1-5	Any hanger, clamp or bracket is missing, loose or broken		
52-1-1	There are any loose, broken, or missing mountings		
52-1-2	Any shock absorber is leaking fluid		

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.