

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/31/2023	Time:	11:09 AM		
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			Corp ID:	251807		
Address of School Corporation:	11260 Cornell Park Dr Suite 700						
City:	Cincinnati	Zip:	45242	County Number:	18		
VIN:	4UZABRFC7LCLJ5476		License Number:	B717T	Bus Number:	M44	
Make of Body:	Freightliner	Year:	2018	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2020
Bus Type:	C		Mileage:	27082			
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-1	There are any loose, broken, or missing mountings
62-1-2	One (1) taillight or one (1) brake light does not function
62-1-9	LED type lights have 25% to 49% pixels inoperable in any one light
35-1-1	A heater motor is not operating properly
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-4	Stop arm does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.