## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		Date:	5/31/2023	Time:	11:11 AM
Name of School C	Corp ID:	251807				
Address of School	ol Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	Zip:	45242		County Number:	18
VIN:	4UZABRFC7LCL	J5476	License Number:	B717T	Bus Number:	M44
Make of Body:	Freightliner Year	: 2018	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2020
Bus Type:	С		Mileage:	27082		
Inspection Status:	0	Inspected By:	Steve Spallinger		PE:	6921

## **Violations - Rejected**

Inspection Code	<u>Description</u>
62-1-9	LED type lights have 25% to 49% pixels inoperable in any one light
62-1-2	One (1) taillight or one (1) brake light does not function
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
52-1-1	There are any loose, broken, or missing mountings

## **Violations - Out of Service**

Inspection Code	<u>Description</u>					
59-2-4	Stop arm does not function properly					

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.