

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/1/2023	Time:	10:30 AM		
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			Corp ID:	251807		
Address of School Corporation:	11260 Cornell Park Dr Suite 700						
City:	Cincinnati	Zip:	45242	County Number:	18		
VIN:	1HA6GUBG8LN001830		License Number:	B716T	Bus Number:	M39	
Make of Body:	Chevrolet	Year:	2020	Make of Chassis:	GMC	Year:	2021
Bus Type:	A1			Mileage:	18878		
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
64-1-6	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.