

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/1/2023	Time: 10:30 AM
Name of School Corporation: AUXILIO SERVICES (MUNCIE)	Corp ID: 251807	
Address of School Corporation: 11260 Cornell Park Dr Suite 700		
City: Cincinnati	Zip: 45242	County Number: 18
VIN: 1HA6GUBG8LN001830	License Number: B716T	Bus Number: M39
Make of Body: Chevrolet	Year: 2020	Make of Chassis: GMC
Year: 2021	Bus Type: A1	Mileage: 18878
Inspection Status: O	Inspected By: Steve Spallinger	PE: 6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
64-1-6	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.