## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	6/2/2023	Time:	9:56 AM
Name of School Corporation: DA		LEVILLE COMMUNITY SCHOOLS		Corp ID:	181940	
Address of School	Corporation:	14300 W 2nd S	St			
City:	Daleville	Zip:	47334		<b>County Number:</b>	18
VIN:	4DRBUAAN6EB417	563	License Number:	5619	Bus Number:	10
Make of Body:	IC Corporation Year:	2012	Make of Chassis:	IC Corporation	Year:	2014
Bus Type:	С		Mileage:	47849		
Inspection Status:	R	Inspected By:	Steve Spallinger		PE:	6921

## **Violations - Rejected**

Inspection Code	Description
57-1-5	Step-well light is missing or inoperative
26-1-4	Not securely mounted
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

## Violations - Out of Service

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.