## REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 6/2/2023 Time: 11:06 AM

Name of School Corporation: DALEVILLE COMMUNITY SCHOOLS Corp ID: 181940

Address of School Corporation: 14300 W 2nd St

City:DalevilleZip:47334County Number:18VIN:4DRBUAAN2BB336670License Number:75066Bus Number:4Make of Body:IC Corporation Year:2010Make of Chassis:IC Corporation Year:2011

Bus Type: C Mileage: 86902

Inspection Status: O Inspected By: Steve Spallinger PE: 6921

# Violations - Rejected

### Inspection Code Description

11-1-2 The front or rear bumper is not properly attached, missing, torn, loose, or altered.

#### **Violations - Out of Service**

Inspection Code Description

7-2-4 Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

#### **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.