## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	6/2/2023	Time:	11:19 AM
Name of School Corporation: Address of School Corporation:		DALEVILLE COMMUNITY SCHOOLS 14300 W 2nd St			Corp ID:	181940	
City:	Daleville		Zip:	47334		County Number:	18
VIN:	1GB3G2BG6C1179	243		License Number:	13378	Bus Number:	23
Make of Body:	Collins Bus Corporation	Year:	2012	Make of Chassis:	Collins Bus Corporation	Year:	2012
Bus Type:	A2			Mileage:	46961		
Inspection Status:	R		Inspected By:	Steve Spallinge	er	PE:	6921

# **Violations - Rejected**

<u>Inspection</u> <u>Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

### **Violations - Out of Service**

## **Inspection Code Description**

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.