REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | | Date: | 6/7/2023 | Time: | 8:09 AM |
|--------------------------------|--------------------------|------|-----------------------|---------------------|-------------------|-------------------|------------|
| Name of School (| Corporation: | LANE | ESVILLE COM | IMUNITY SCH. C | ORP | Corp ID: | 313160 |
| Address of School Corporation: | | | 2725 Crestview Ave NE | | | | |
| City: | Lanesville | | Zip: | 47136 | | County Number: | 31 |
| VIN: | 4DRBBAAP73B581 | 649 | | License Number: | bbbb | Bus Number: | 3 |
| Make of Body: | Blue Bird Corporation | Year | 2003 | Make of Chassis: | IC Corporation | Year: | 2004 |
| Bus Type: | С | | | Mileage: | 140787 | | |
| Inspection Status | s: R | | Inspected By: | Troy Boyd | | PE: | 5171 |

Violations - Rejected

Inspection
CodeDescription23-1-3Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any
direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.