

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	6/14/2023	<b>Time:</b>	10:47 AM
<b>Name of School Corporation:</b>	VIGO COUNTY SCHOOL CORPORATION			<b>Corp ID:</b>	848030
<b>Address of School Corporation:</b>	3250 Maple Ave				
<b>City:</b>	Terre Haute	<b>Zip:</b>	47804	<b>County Number:</b>	84
<b>VIN:</b>	4DRBUAAN6CB623723	<b>License Number:</b>	2138	<b>Bus Number:</b>	1182
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2011	<b>Make of Chassis:</b>	IC Corporation
		<b>Year:</b>		<b>Year:</b>	2012
<b>Bus Type:</b>	C	<b>Mileage:</b>	106653		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Byron Goodman	<b>PE:</b>	7008

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
33-1-1	The grill has any exposed edges that may cause injury
14-1-1	See Notes: Any defect inspector deems a violation not listed
34-1-1	Any headlight is inoperative
11-1-1	The front bumper does not extend to the edge of the fenders
64-1-1	Turn signals are not properly mounted
64-1-4	Any front turn signal does not function properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
11-2-2	A bumper does not meet manufactures specifications

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**