REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/28/2023	**Time:**	7:35 AM
Name of School Corporation:	SCHOOL CITY OF HOBART SERVICE CTR			**Corp ID:**	454730
Address of School Corporation:	200 S Hobart Rd				
City:	Hobart	**Zip:**	46342	**County Number:**	45
VIN:	4DRBUAAN1DB304974	**License Number:**	4764	**Bus Number:**	2
Make of Body:	IC Corporation **Year:** 2012	**Make of Chassis:**	IC Corporation	**Year:**	2013
Bus Type:	C	**Mileage:**	110309		
Inspection Status:	R	**Inspected By:**	Tim Grayson	**PE:**	7558

Violations - Rejected

Inspection Code	Description
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.