

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 6/28/2023	<b>Time:</b> 9:10 AM	
<b>Name of School Corporation:</b> ARGOS COMMUNITY SCHOOLS	<b>Corp ID:</b> 505470		
<b>Address of School Corporation:</b> 410 N First St			
<b>City:</b> Argos	<b>Zip:</b> 46501	<b>County Number:</b> 50	
<b>VIN:</b> 4DRBUSKPX9B681719	<b>License Number:</b> 33093	<b>Bus Number:</b> 4	
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2007	<b>Make of Chassis:</b> IC Corporation	<b>Year:</b> 2009
<b>Bus Type:</b> C	<b>Mileage:</b> 142095		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Travis Harrold	<b>PE:</b> 8022	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
24-1-1	The bus body has rust or rusted through areas which may weaken the body

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**