## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:6/30/2023Time:9:11 AMName of School Corporation:CULVER COMMUNITY SCHOOLS CORP.Corp ID:505455

Address of School Corporation: PO Box 231

City:CulverZip:46511County Number:50VIN:4DRBUC8P3GB192038License Number:2494Bus Number:06Make of Body:IC Corporation Year:2015Make of Chassis:IC Corporation Year:2016

Bus Type: C Mileage: 90627

Inspection Status: R Inspected By: Travis Harrold PE: 8022

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

2-1-1 Required back-up lights do not function.

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.