REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	6/30/2023	Time:	10:48 AM
Name of School Co	orporation:	CULVE	R COMMUNIT	TY SCHOOLS COR	P.	Corp ID:	505455
Address of School	Corporation:	F	PO Box 231				
City:	Culver	Z	Zip:	46511		County Number:	50
VIN:	4DRBUSKP9	3B33845	54	License Number:	74975	Bus Number:	20
Make of Body:	IC Corporation	Year: 2	2010	Make of Chassis:	IC Corporation	Year:	2011
Bus Type:	С			Mileage:	135725		
Inspection Status:	0	h	nspected By:	Travis Harrold		PE:	8022

Violations - Rejected

Inspection CodeDescription13-1-1Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.