

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Re-Inspection	<b>Date:</b>	7/5/2023	<b>Time:</b>	10:09 AM
<b>Name of School Corporation:</b>	MUNCIE COMMUNITY SCHOOLS	<b>Corp ID:</b>	181970		
<b>Address of School Corporation:</b>	2501 N Oakwood				
<b>City:</b>	Muncie	<b>Zip:</b>	47304	<b>County Number:</b>	18
<b>VIN:</b>	1GB6G3AGXA1141385	<b>License Number:</b>	83104	<b>Bus Number:</b>	8
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2010	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>		<b>Year:</b>	2010	<b>Mileage:</b>	42482
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Steve Spallinger	<b>PE:</b>	6921

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-2	Excessive effort is needed to open the emergency door

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description