

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|----------------------|-------------------------|-------------------------|
| Type of Inspection: | Annual | Date: | 7/6/2023 | Time: | 10:05 AM |
| Name of School Corporation: | UNION-NORTH UNITED SCHOOL CORP | | | Corp ID: | 717215 |
| Address of School Corporation: | 22601 Tyler Rd | | | | |
| City: | Lakeville | Zip: | 46536 | County Number: | 71 |
| VIN: | 1FD4E45P38DB13709 | License Number: | 60375 | Bus Number: | 35 |
| Make of Body: | Ford | Year: | 2008 | Make of Chassis: | Collins Bus Corporation |
| Year: | 2008 | | Mileage: | 183273 | |
| Bus Type: | A1 | | Inspected By: | Travis Harrold | |
| Inspection Status: | O | | PE: | 8022 | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 63-2-5 | Any rear tire has less than 1/32 inch tread depth when measured in any two adjacent major grooves |

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.