## REPORT OF SCHOOL BUS INSPECTION

Type of 10:03 Time: Annual Date: 7/10/2023 Inspection: AM Name of School Corporation: CROWN POINT COMM. SCHOOL CORP. 454660 Corp ID: **Address of School Corporation:** 1151 E Summit County City: Crown Point Zip: 46307 45 Number: License VIN: 1T7Y84D24P1195445 95437 Bus Number: 301 Number: Thomas Built Buses, Year: 2022 Thomas Built Buses, Year: Make of Make of Body: 2023 Chassis: Inc. **Bus Type:** D Mileage: 4784 Inspection Inspected PE: Α Tim Grayson 7558 Status: By:

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.