

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Registration	<b>Date:</b>	7/18/2023	<b>Time:</b>	11:32 AM
<b>Name of School Corporation:</b>	JOY'S HELPING HAND CHILD CARE	<b>Corp ID:</b>	222		
<b>Address of School Corporation:</b>	3807 W. Michigan St,				
<b>City:</b>	Indianapolis	<b>Zip:</b>	46224	<b>County Number:</b>	49
<b>VIN:</b>	1GBHG31C581137356	<b>License Number:</b>	B313U	<b>Bus Number:</b>	13
<b>Make of Body:</b>	Collins Bus Corporation	<b>Year:</b>	2008	<b>Make of Chassis:</b>	Collins Bus Corporation
<b>Bus Type:</b>	A2	<b>Mileage:</b>	74534	<b>Year:</b>	2008
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nick Cox	<b>PE:</b>	8795

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
57-1-5	Step-well light is missing or inoperative
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals
68-1-1	Washers do not function properly in any manner
29-1-5	Prohibited area sign is missing or obscured
29-1-4	Prohibited area line is missing or improper
43-1-8	Any required lettering is missing or faded.
49-1-1	The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
50-2-2	The seat belt cutter does not have a full width handgrip, with a protective blade to minimize risk
10-2-2	The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design)
45-2-1	The bus with a body build date of January 1, 2006 or after is not equipped with the noise suppression switch. EXEMPTION Type A buses - w/out noise making devices other OEM accessories not including two-way, AM/FM, Satellite, or similar.
8-2-1	There is no brake certification, or the certification has expired or is not signed
23-2-1	Exhaust leak exceeding one (1) inch measurable in any direction or half (½) inch in diameter.

### **Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**