

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 7/26/2023 **Time:** 10:52 AM
Name of School Corporation: UNION SCHOOL CORPORATION **Corp ID:** 686795
Address of School Corporation: 8707 W US 36
City: Modoc **Zip:** 47358 **County Number:** 68
VIN: 4DRBUSKP2EB417047 **License Number:** 24714 **Bus Number:** 2
Make of Body: IC Corporation **Year:** 2012 **Make of Chassis:** IC Corporation **Year:** 2014
Bus Type: C **Mileage:** 69288
Inspection Status: O **Inspected By:** Steve Spallinger **PE:** 6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-3	Any required padding is missing
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.