REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Re-Inspection | | | Date: | 7/26/2023 | Time: | 11:14 AM |
|--|-----------------------------|--|------------------|---------------------|--------------|-------------------|-------------|
| Name of School Corporation: Address of School Corporation: | | UNION SCHOOL CORPORATION 8707 W US 36 | | | Corp ID: | 686795 | |
| City: | Modoc | | Zip: | 47358 | | County Number: | 68 |
| VIN: | 4uzabrdu6dcbr8554 | | | License Number: | 2737 | Bus Number: | 21 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | : 2011 | Make of Chassis: | Freightliner | Year: | 2012 |
| Bus Type: | С | | | Mileage: | 238033 | | |
| Inspection Status: | 0 | | Inspected By: | Steve Spallinger | | PE: | 6921 |

Violations - Rejected

| <u>Inspection</u> <u>Code</u> | <u>Description</u> |
|----------------------------------|--|
| 50-1-2 | The seat belt cutter is not secured using a positive fastening method. |
| 95-1-6 | Does not have a circuit breaker of fuse connecting the lift motor to the power source |
| 41-1-5 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.