

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|------------------------------|---------------|----------------|------------------|--------------|
| Type of Inspection: | Registration | Date: | 7/26/2023 | Time: | 11:31 AM |
| Name of School Corporation: | HOLY TRINITY CATHOLIC SCHOOL | | | Corp ID: | 19A865 |
| Address of School Corporation: | 990 Church Ave | | | | |
| City: | Jasper | Zip: | 47546 | County Number: | 19 |
| VIN: | 4UZAAXCS87CW45099 | | | License Number: | NBHOLY2 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2006 | Make of Chassis: | Freightliner |
| Bus Type: | C | | | Year: | 2007 |
| Inspection Status: | R | Inspected By: | Philip Lubbers | PE: | 7703 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 11-1-3 | Bumpers are not black |
| 43-1-8 | Any required lettering is missing or faded. |
| 62-1-2 | One (1) taillight or one (1) brake light does not function |
| 65-1-1 | Any lens is cracked, broken or discolored |
| 28-1-2 | The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment." |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.