

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	8/8/2023	Time:	11:16 AM
Name of School Corporation:	KOKOMO SCHOOL CORPORATION	Corp ID:	343500		
Address of School Corporation:	620 W Deffenbaugh				
City:	Kokomo	Zip:	46901	County Number:	34
VIN:	4DRBWAAR4FB143424	License Number:	7186	Bus Number:	221
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation
Year:			2015	Year:	2015
Bus Type:	D	Mileage:	100857	PE:	7018
Inspection Status:	O	Inspected By:	Randy McPike		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-2	Any seat back or bottom is loose

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus
7-2-3	The required low air-pressure warning device fails to operate properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.