

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 8/8/2023	Time: 10:59 AM
Name of School Corporation: AVON COMMUNITY SCHOOLS	Corp ID: 323315	
Address of School Corporation: 7203 E HWY 36		
City: Avon	Zip: 46123	County Number: 32
VIN: 4DRBWTAR7PB003896	License Number: 25820	Bus Number: 88
Make of Body: IC Corporation	Year: 2022	Make of Chassis: IC Corporation
Year: 2023	Mileage: 8716	PE: 7415
Bus Type: D	Inspected By: Joel Flores	
Inspection Status: R		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.