## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	8/8/2023	Time:	11:11 AM
Name of School Co	orporation: AVON	<b>COMMUNITY</b>	SCHOOLS		Corp ID:	323315
Address of School	Corporation:	7203 E HWY 3	6			
City:	Avon	Zip:	46123		<b>County Number:</b>	32
VIN:	4DRBWTAR9PB0039	902	License Number:	25918	Bus Number:	101
Make of Body:	IC Corporation Year:	2022	Make of Chassis:	IC Corporation	Year:	2023
Bus Type:	D		Mileage:	9416		
Inspection Status:	A	Inspected By:	Joel Flores		PE:	7415

**Violations - Rejected** 

Inspection Code Description

Violations - Out of Service

Inspection Code Description

## Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.