REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | Date: | 8/10/2023 | Time: | 10:24 AM |
|---|--------------------------|---|---------------------|--------------------------|-------------------|-------------|
| Name of School Corporation: Address of School Corporation: | | AVON COMMUNITY SCHOOLS 7203 E HWY 36 | | Corp ID: | 323315 | |
| City: | Avon | Zip: | 46123 | | County Number: | 32 |
| VIN: | 1BAKCCPA8GF322449 | | License Number: | 10389 | Bus Number: | 85 |
| Make of Body: | Blue Bird Corporation | Year: 2015 | Make of Chassis: | Blue Bird Corporation | Year: | 2016 |
| Bus Type: | С | | Mileage: | 91871 | | |
| Inspection Status: | A | Inspected By: | Jeff Stone | | PE: | 8184 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.