

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	8/10/2023	Time:	11:52 AM
Name of School Corporation:	FIRST STUDENT-GARY			Corp ID:	
Address of School Corporation:	1501 Michigan				
City:	Gary	Zip:	46402	County Number:	45
VIN:	4DRBUP1N9HB474413			License Number:	105399SB
Make of Body:	IC Corporation	Year:	2016	Make of Chassis:	IC Corporation
Bus Type:	C			Year:	2017
Inspection Status:	O	Inspected By:	Nathan Sherer	PE:	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-1	The seat belt cutter is not located within the driver's view and reach
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.