

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 8/10/2023 **Time:** 9:25 AM
Name of School Corporation: DECATUR COUNTY COMM. SCHOOL **Corp ID:** 161655
Address of School Corporation: 1645 W SR 46
City: Greensburg **Zip:** 47240 **County Number:** 16
VIN: 4UZABRDT4ACAN3158 **License Number:** 1234 **Bus Number:** 40
Make of Body: Freightliner **Year:** 2009 **Make of Chassis:** Freightliner **Year:** 2010
Bus Type: C **Mileage:** 148861
Inspection Status: O **Inspected By:** Chris Clark **PE:** 6665

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 24-2-1 | There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)). |
| 7-2-1 | There is no brake certification form the certification is expired or is not signed within the six-month requirement |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.