

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 8/14/2023 Time: 9:56 AM
Name of School Corporation: FIRST STUDENT-GARY Corp ID:
Address of School Corporation: 1501 Michigan
City: Gary Zip: 46402 County Number: 45
VIN: 4DRBUP1N7HB474345 License Number: 12813 Bus Number: 411
Make of Body: IC Corporation Year: 2016 Make of Chassis: IC Corporation Year: 2017
Bus Type: C Mileage: 58571
Inspection Status: O Inspected By: Nathan Sherer PE: 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured using a positive fastening method.
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
59-1-4	LED type lights have 25% to 49% pixels inoperable in any one light. (NOTE: one letter in the word "STOP" equals one light)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.