

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 8/14/2023 Time: 10:24 AM
Name of School Corporation: FIRST STUDENT-GARY Corp ID:
Address of School Corporation: 1501 Michigan
City: Gary Zip: 46402 County Number: 45
VIN: 4DRBUP1N3HB474343 License Number: 12808 Bus Number: 409
Make of Body: AmTran Year: 2016 Make of Chassis: IC Corporation Year: 2017
Bus Type: C Mileage: 61451
Inspection Status: O Inspected By: Nathan Sherer PE: 7029

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 7-1-3 | Air leak at proper connection |
| 70-1-10 | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |
| 50-1-2 | The seat belt cutter is not secured using a positive fastening method. |
| 41-1-4 | There is debris in the bus. (needs cleaned/includes dirt) |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.