REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/14/2023	**Time:**	10:31 AM
Name of School Corporation:	FIRST STUDENT-GARY			**Corp ID:**	
Address of School Corporation:	1501 Michigan				
City:	Gary	**Zip:**	46402	**County Number:**	45
VIN:	4DRBUP1N6HB474336	**License Number:**	12798	**Bus Number:**	402
Make of Body:	IC Corporation **Year:** 2016	**Make of Chassis:**	IC Corporation	**Year:**	2017
Bus Type:	C	**Mileage:**	65622		
Inspection Status:	O	**Inspected By:**	Nathan Sherer	**PE:**	7029

Violations - Rejected

Inspection Code	Description
50-1-2	The seat belt cutter is not secured using a positive fastening method.
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
57-1-5	Step-well light is missing or inoperative
34-1-1	Any headlight is inoperative

Violations - Out of Service

Inspection Code	Description
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.