

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	8/14/2023	Time:	10:31 AM
Name of School Corporation:	FIRST STUDENT-GARY	Corp ID:			
Address of School Corporation:	1501 Michigan				
City:	Gary	Zip:	46402	County Number:	45
VIN:	4DRBUP1N6HB474336	License Number:	12798	Bus Number:	402
Make of Body:	IC Corporation	Year:	2016	Make of Chassis:	IC Corporation
		Year:		Year:	2017
Bus Type:	C	Mileage:	65622		
Inspection Status:	O	Inspected By:	Nathan Sherer	PE:	7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured using a positive fastening method.
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
57-1-5	Step-well light is missing or inoperative
34-1-1	Any headlight is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.