

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 8/14/2023      **Time:** 10:52 AM  
**Name of School Corporation:** FIRST STUDENT-GARY      **Corp ID:**  
**Address of School Corporation:** 1501 Michigan  
**City:** Gary      **Zip:** 46402      **County Number:** 45  
**VIN:** 4DRBUP1NXHB474341      **License Number:** 12792      **Bus Number:** 407  
**Make of Body:** IC Corporation      **Year:** 2016      **Make of Chassis:** IC Corporation      **Year:** 2017  
**Bus Type:** C      **Mileage:** 46152  
**Inspection Status:** O      **Inspected By:** Nathan Sherer      **PE:** 7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-5	There are any decals or stickers, except those required by law, in the windshield or in the windows to the immediate right or left of the driver
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
50-1-2	The seat belt cutter is not secured using a positive fastening method.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**