

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                              |                        |            |                         |          |              |      |
|---------------------------------------|------------------------------|------------------------|------------|-------------------------|----------|--------------|------|
| <b>Type of Inspection:</b>            | Re-Inspection                | <b>Date:</b>           | 8/17/2023  | <b>Time:</b>            | 10:59 AM |              |      |
| <b>Name of School Corporation:</b>    | ZIONSVILLE COMMUNITY SCHOOLS |                        |            | <b>Corp ID:</b>         | 60630    |              |      |
| <b>Address of School Corporation:</b> | 9770 E CR 600S               |                        |            |                         |          |              |      |
| <b>City:</b>                          | Zionsville                   | <b>Zip:</b>            | 46077      | <b>County Number:</b>   | 6        |              |      |
| <b>VIN:</b>                           | 1FDWE35P26DB15232            | <b>License Number:</b> | 71975      | <b>Bus Number:</b>      | V6       |              |      |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.     | <b>Year:</b>           | 2006       | <b>Make of Chassis:</b> | Ford     | <b>Year:</b> | 2006 |
| <b>Bus Type:</b>                      | B                            | <b>Mileage:</b>        | 95277      |                         |          |              |      |
| <b>Inspection Status:</b>             | A                            | <b>Inspected By:</b>   | Jeff Stone | <b>PE:</b>              | 8184     |              |      |

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**