REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	8/21/2023	Time:	11:32 AM
Name of School Co	orporation: BLA	CKFORD COUN	TY SCHOOLS		Corp ID:	50515
Address of School	Corporation:	668 W CR 200	S			
City:	Hartford City	Zip:	47348		County Number:	5
VIN:	4DRBUAAN1CB46	1841	License Number:	337	Bus Number:	111
Make of Body:	IC Corporation Year	r: 2011	Make of Chassis:	IC Corporation	Year:	2012
Bus Type:	С		Mileage:	127933		
Inspection Status:	R	Inspected By:	Steve Spallinger		PE:	6921

Violations - Rejected

Inspection CodeDescription46-1-5Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.